

**BIRLA INSTITUTE OF TECHNOLOGY, MESRA, RANCHI
(END SEMESTER EXAMINATION)**

**CLASS: BTech
BRANCH: Production**

**SEMESTER : VI
SESSION: SP/2023**

SUBJECT: PE314 STATISTICAL QUALITY CONTROL

TIME: 3 Hours

FULL MARKS: 50

INSTRUCTIONS:

1. The question paper contains 5 questions, each of 10 marks and total of 50 marks.
2. Attempt all questions.
3. The missing data, if any, may be assumed suitably.
4. Before attempting the question paper, be sure that you have got the correct question paper.
5. Tables/Data handbook/Graph paper etc. to be supplied to the candidates in the examination hall.

CO BL

- Q.1(a) Which measure of central tendency and dispersion will you suggest for a sample of data containing extreme fluctuations? Why? [2]
- Q.1(b) What are the components of the cost of quality? Define optimum cost of quality. [3]
- Q.1(c) Why is there a difference between the formula used for calculating the standard deviation of a population and that of a sample? Find the standard deviation of group data given below: [5]

X_i	3	5	7	8	9
f_i	2	3	2	2	1

- Q.2(a) When dealing with a variable quality characteristic, Why is it usually necessary to monitor both \bar{X} -bar and R or S chart? [2]
- Q.2(b) Explain process capability. What does it tell us? A process has a mean of 45.5 and a standard deviation of 0.9. The product has a specification of 45.0 ± 3.0 . Find the process capability index(Cpk) . [2]
- Q.2(c) Parts manufactured by an injection moulding process are subjected to a compressive strength test. Ten samples of five parts each are collected, and the compressive strengths in psi are shown in Table. [6]

Number	1	2	3	4	5	6	7	8	9	10
x1	83	88.6	85.7	80.8	83.4	75.3	74.5	79.2	80.5	75.7
x2	81.2	78.3	75.8	74.4	78.4	79.9	78	84.4	86.2	75.2
x3	78.7	78.8	84.3	82.5	82.6	87.3	80.8	81.5	76.2	71.1
x4	75.7	71	75.2	74.1	78.2	89.7	73.4	86	64.1	82.1
x5	77	84.2	81	75.7	78.9	81.8	79.7	74.5	80.2	74.3

- i) Compute control limits for the \bar{X} -bar & R chart.
- ii) Compute control limits for the S chart.

For $n=5$: $A=1.342$, $A_2=0.577$, $A_3=1.427$, $B_3=0$, $B_4=2.089$, $B_5=0$, $B_6=1.964$, $c_4=0.94$, $D_1=0$, $D_2=4.918$, $D_3=0$, $D_4=2.114$, $d_3=0.864$

- Q.3(a) Consider a single sampling plan $N = 1500$, $n = 200$, $c = 3$. Construct the OC curve. If the acceptable quality level is 0.05% nonconforming and the limiting quality level is 6% nonconforming, describe the protection offered by the plan at these quality levels. [5]
- Q.3(b) Consider a double sampling plan given by the following parameters: $N=2200$, $n_1 = 60$, $c_1 = 0$, $r_1 = 5$, $n_2 = 100$, $c_2 = 6$, $r_2 = 7$. Find the probability of accepting lots that are 3% non-conforming. What is the probability of accepting a lot on the first sample? What is the probability of making a decision on the first sample? [5]
- Q.4(a) The specifications of a steel shaft are 6.40 ± 0.10 mm. The device sometimes fails when the shaft exceeds the specification. When failure occurs, repair or replacement is necessary at an average cost of Rs.95. [5]
- i) What is the loss coefficient k ?
 - ii) What is the loss function equation?
 - iii) What is the loss at 6.45 mm?

PTO

Q.4(b) The table shows you the L8 OA for predicting the weld hardness of Submerged Arc Welding (SAW) where the quality characteristic is larger-than-the-better type. In this experiment, three factors having two levels are taken that affect the weld hardness. [5]

Experiment No.	Factors		Weld Hardness
	A	B	
1	1	1	51
2	1	2	50
3	2	1	43
4	2	2	46

- i) Calculate the S/N ratio for each experiment.
- ii) Draw the main effects plot for S/N ratios.
- iii) Determine the optimal parameter setting that enhances hardness.

Q.5(a) Define Quality circle. Explain its implementation process. [3]

Q.5(b) What is a 'Six Sigma'? Why is it assumed that the Six Sigma process would produce about 3.4 ppm defective in place of 0.002 ppm defective? [3]

Q.5(c) What is ISO? What is the main purpose of ISO 9000? List the ISO 9000 series of standards. [4]

:::::26/04/2023 M:::::